

Vehicle data

Vehicle type	Passenger car
Brand	BMW
model	650i
Vehicle identification number	CN70162
Vehicle identification number (17 digits)	WBAEK11020EXAMPLE
Development code	E64
Engine	N62/TU
Engine number	50493903
Transmission number	4295765
Production date	25-Oct-2006
First registration date	30-Nov-2006
Paint code	0475
Colour	black-sapphire metallic
Upholstery code	LEGE
Upholstery	Leather "Pearl/Precision"/creambeige
Control type	EK21
Type code	EK21
Teleservices	
Teleservice capability	Yes
BMW ConnectedDrive contract	No
Domestic retailer	No
Service history via Teleservices	No
Remote KeyRead capability	No
Optional equipment	
01CA Selection of COP-relevant vehicles	
0205 Automatic transmission	
0217 Active steering	
0248 Steering wheel heater	
0255 Sports leather steering wheel	
0302 Alarm system	
0322 Comfort access	
0323 Soft-Close-Automatic doors	
0388 Softtop, black	
0423 Floor mats velours	

0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0436 Fine wood trim
0459 Seat adjustment, electric, with memory
0494 Seat heating driver/passenger
0502 Headlight cleaning system
0508 Park Distance Control (PDC)
0522 Xenon Light
0524 Adaptive Headlights
0534 Automatic air conditioning
0540 Cruise control
0548 Kilometre speedo
0563 Light package
0595 BMW LA wheel, ellipsoid styling 121
05AC High-beam assistant
0609 Navigation system Professional
0610 Head-up display
0612 BMW Assist
0616 BMW Online
0620 Voice control
0633 Preparation, mobile phone, Business
0672 CD changer for 6 CDs
0677 HiFi system Professional DSP
0698 Area-Code 2 for DVD
06AA BMW TeleServices
07R7 Innovation package
0801 National version Germany
0851 Language version German
0863 Dealer List Europe
0879 On-board literature, German
08SA Navigation access request,country-spec.
08SP Control unit COP
B110
HOS3
NMUW

Later installed optional equipment:

This vehicle has no retrofitting.

Technical campaigns

There are no technical campaigns available.

Histories

Date

Type

Vehicle mileage

Retailer

Overview

31/03/2021

Repair

173062 Km

04670

• Job

Job

Description:

Considered as a repeat visit

No

Customer's own words

Performing vehicle test
Flat rate unit | 00 00 006
-4 FRU

16/03/2020

Repair

173062 Km

04670

- Job
- Job
- Job
- Job
- Job
- Job

Job

Description:

Considered as a repeat visit

No

Customer's own words

Performing vehicle test
Flat rate unit | 00 00 006
4 FRU

Job

Description:

Considered as a repeat visit

No

Customer's own words

Removing and installing or replacing integrated supply module
Flat rate unit | 12 52 505
5 FRU

Integrated supply module

Part | 12 52 7 510 638

1

Cable connector

Part | 61 13 8 353 747

3

Job

Description:

Considered as a repeat visit

No

Customer's own words

Job time without allowance for / fuel conditioning
Flat rate unit | 13 99 000
3 FRU

Job

Description:

Considered as a repeat visit

No

Customer's own words

Removing and installing/sealing right cylinder head cover

Flat rate unit | 11 12 006

30 FRU

Spark plug, High Power

Part | 12 12 2 158 252

8

Gasket set, cylinder head cover

Part | 11 12 7 513 195

1

Job

Description:

Considered as a repeat visit

No

Customer's own words

Replacing engine section of wire harness

Flat rate unit | 12 51 001

70 FRU

wiring harness, engine ignition module

Part | 12 51 7 558 199

1

Wiring harness, injection valve

Part | 12 51 7 549 051

1

Job

Description:

Considered as a repeat visit

No

Customer's own words

Vehicle surface wash

Flat rate unit | 00 11 319

0 FRU

Motorsteuergerät geprüft/ nachgelötet

Flat rate unit | 99 99 999

1 FRU

16/12/2019

Repair

172548 Km

04670

- Job
- Job

Job

Description:

Considered as a repeat visit

No

Customer's own words

Job time without allowance for / engine

Flat rate unit | 11 99 000

58 FRU

Performing vehicle test

Flat rate unit | 00 00 006

4 FRU

Job

Description:

Considered as a repeat visit

No

Customer's own words

Replacing right cylinder head gasket

Flat rate unit | 11 12 111

141 FRU

O-ring

Part | 13 64 1 437 487

8

O-ring, grey

Part | 13 64 7 509 752

8

Oil pressure switch

Part | 12 61 8 611 273

1

Profile-gasket

Part | 13 54 7 510 433

1

O-ring

Part | 11 66 7 509 080

1

Spark plug, High Power

Part | 12 12 2 158 252

1

Central screw

Part | 11 36 7 501 423

2

Profile-gasket

Part | 11 61 7 537 999

8

Gasket Steel

Part | 11 14 7 506 424

1

Chain tensioner

Part | 11 31 1 439 552

1

Gasket Asbestos Free

Part | 11 13 1 315 154

1

Gasket right asbesto-free

Part | 11 14 1 312 618

1

Cylinder head gasket asbestos-free

Part | 11 12 7 530 256

1

Set Bolt Cylinder Head

Part | 11 12 7 583 113

1

O-ring

Part | 07 11 9 903 596

2

Sealing compound Drei Bond 1209

Part | 07 58 9 062 376

1

04/11/2019

Repair

172104 Km

04670

- Job
- Job
- Job
- Job
- Job
- Job
- Job

Job

Description:

Considered as a repeat visit

No

Customer's own words

Job time without allowance for / engine

Flat rate unit | 11 99 000

24 FRU

Diagnosing cylinder damage with endoscope

Flat rate unit | 11 11 501

21 FRU

Checking absolute compression of all cylinders

Flat rate unit | 11 00 045

24 FRU

Performing vehicle test

Flat rate unit | 00 00 006

18 FRU

Job

Description:

Considered as a repeat visit

No

Customer's own words

Removing and installing/sealing right cylinder head cover
Flat rate unit | 11 12 006
45 FRU
Gasket set, cylinder head cover
Part | 11 12 7 513 194
1

Job

Description:

Considered as a repeat visit

No

Customer's own words

Removing and installing/renewing all spark plugs
Flat rate unit | 12 12 011
14 FRU
Spark plug, High Power
Part | 12 12 2 158 252
1

Job

Description:

Considered as a repeat visit

No

Customer's own words

Replacing one ignition coil
Flat rate unit | 12 13 511
6 FRU
Ignition coil
Part | 12 13 8 616 153
4

Job

Description:

Considered as a repeat visit

No

Customer's own words

Removing and installing/replacing both exhaust manifolds
Flat rate unit | 18 40 530
24 FRU
Collar nut
Part | 18 10 7 523 805
4

Job

Description:

Considered as a repeat visit

No

Customer's own words

Replacing both camshaft sensors of the intake camshafts
Flat rate unit | 12 14 528
10 FRU

O-ring
Part | 12 14 1 748 398
2
Radiator cap
Part | 17 11 7 639 021
1

Job

Description:

Considered as a repeat visit

No

Customer's own words

Sealing/replacing both control valves for engine venting

Flat rate unit | 11 15 030

8 FRU

Repair kit, pressure regulating valve

Part | 11 12 7 547 058

2

sealing

Part | 11 12 7 518 420

1

29/11/2006

Repair

1 Km

00081

- Job
- Job
- Job

Job

Description:

Considered as a repeat visit

No

Customer's own words

Windshield washer antifreeze

Part | 83 12 0 404 498

1

DVD Road map, Europa Professional

Part | 65 90 0 418 746

1

Job

Description:

Considered as a repeat visit

No

Customer's own words

Free pre-delivery check

Flat rate unit | 00 00 009

8 FRU

Job

Description:

Considered as a repeat visit

No

Customer's own words

Suspension block delivery inspection

Flat rate unit | 00 00 741

1 FRU